

Our Ref: SW/LS/GL 19 September 2018

<u>Report 328461</u> <u>Page 1 of 2</u>

Contrado Imaging Limited Unit 7 Space Business Park Abbey Road Park Royal London NW10 7SU

Contact: Chris Childs: Annie Antoniou

DATE RECEIVED : 11 SEP 2018
QUALITY/REFERENCE : FR VELOUR
REPUTED FIBRE CONTENT : NOT GIVEN
FABRIC DESCRIPTION : WOVEN
COLOUR/DESIGN : BLACK

PERFORMANCE STANDARD : GENERAL



REQUEST: Martindale abrasion

- Wlenn

LSheridan

S. WISEMAN LABORATORY DIRECTOR

L. SHERIDAN LABORATORY MANAGER

This report may not be reproduced except in full without the written approval of HSTTS. In all circumstances results of tests are implied as referring only to the sample supplied and should not be construed or interpreted on any other basis. The comments given in the report are for guidance only and are not a part of the results. Where specified in a test method, preconditioning in accordance with ISO 139 is not carried out as samples are exposed to the conditioning atmosphere specified within ISO 139 for a minimum of 16 hours prior to test.





19 September 2018

<u>Page 2 of 2</u>

PHYSICAL

BS EN 14465:2003 Annex A Abrasion Resistance

12 kPa load.

12 Ki & 1046.	
	Number of rubs to breakdown:
	Head 1 20,000+
	Head 2 20,000+
	Head 3 20,000+
	Head 4 20.000+

BS EN 14465:2003 Annex A Abrasion Resistance

12 kPa load.

Number of rubs to breakdown:
Head 1 30,000+
Head 2 30,000+
Head 3 30,000+
Head 4 30,000+

